

Pictures from the quick clay slide in Rissa, Norway 29 April 1978



Above: Areal view of the slide from the south

Top right: The cause of the slide; excavation material for extension of farm house placed along shoreline of lake. The barn can be seen on the northern edge of the slide on the large picture

Middle right: Demolished farm along western slide scar

Bottom right: Eastern slide scar towards south

